

TIF352U0089

Temperature Sensor for Contactless Temperature Measurement



Operating Instructions

Table of Contents

1. General	4
1.1. Information Regarding these Instructions	4
1.2. Explanation of Symbols	4
1.3. Limitation of Liability	5
1.4. Copyrights	5
2. For Your Safety	6
2.1. Use for Intended Purpose	6
2.2. Use for Other than the Intended Purpose	7
2.3. Personnel Qualifications	7
2.4. Modification of Products	7
2.5. General Safety Precautions	7
2.6. Laser/LED Warnings	7
2.7. Approvals and Protection Class	8
3. Technical Data	8
3.1. Field of Vision	9
3.2. Housing Dimensions	10
3.3. Connection Diagram	11
3.4. Complementary Products (see catalog)	11
3.5. Layout	12
3.6. Control Panel	12
3.7. Scope of Delivery	13
4. Transport and Storage	13
4.1. Transport	13
4.2. Storage	13
5. Installation and Electrical Connection	14
5.1. Installation	14
5.2. Electrical Connection	15
6. Overview of Functions	15
6.1. Default Settings	15
6.2. Function Definitions	16
6.3. Menu Structure	16
7. Settings	19
7.1. run (display mode)	19
7.2. PlnF (pin function)	19

7.3. AnA (select analog voltage output or current output)	19
7.4. A.Lo (temperature for 4 mA/0 V)	20
7.5. A.hI (temperature for 20 mA/10 V)	20
7.6. SP1 (set switching point or switching temperature 1)	21
7.7. OFn1 (select output function)	21
7.8. SL1 (select switching logic)	21
7.9. SP2 (set switching point or switching temperature 2)	22
7.10. OFn2 (select output function)	22
7.11. SL2 (select switching logic)	22
7.12. EP (expert menu)	23
7.13. Lasr (set laser function)	23
7.14. d.U (select temperature unit of measure)	24
7.15. EF (adjust emission factor)	24
7.16. S.EF (determine emission factor with a reference device)	24
7.17. rESP (set response time)	25
7.18. SEr.O (activate or deactivate the serial port)	25
7.19. rES (reset)	25
7.20. Diagnostics	26
8. RS 232 Port	26
9. Maintenance Instructions	26
10. Proper Disposal	26
11. Exclusion of Liability	27
12. Appendix	28
12.1. Operating Instructions Change Index	28
12.2. Emission Factor	28
12.3. EC Declaration of Conformity	30

1. General

1.1. Information Regarding these Instructions

- These instructions are intended for the product with the order code TIF352U0089.
- They make it possible to work with the product safely and efficiently.
- These instructions are an integral part of the product and must be kept on hand for the entire duration of its service life.
- Furthermore, local accident prevention regulations and national work safety regulations must also be observed.



Note!

The operating instructions must be read carefully before using the product and kept on file for future reference!

1.2. Explanation of Symbols

- Safety instructions and warnings are emphasized by means of symbols and keywords.
- Safe use of the product is only possible if these safety instructions and warnings are observed.
- Safety instructions and warnings are laid out on the basis of the following principle:



Keyword!

Type and source of danger!

Possible consequences in the event that instructions or warnings are disregarded.
– Risk prevention measure.

The meanings of the keywords and the scope of the associated hazards are explained below:



Danger!

This keyword indicates a hazard with a high degree of risk which, if not avoided, results in death or severe injury.



Warning!

This keyword indicates a hazard with a moderate degree of risk which, if not avoided, may result in death or severe injury.



Caution!

This keyword indicates a hazard with a low degree of risk which, if not avoided, may result in minor or moderate injury.



Attention!

This keyword indicates a potentially hazardous situation which, if not avoided, may result in property damage.



Note!

A note draws attention to useful tips and suggestions, as well as information regarding efficient and error-free operation.

1.3. Limitation of Liability

- The product was developed in consideration of the current state-of-the-art and applicable standards and directives. The product is subject to change without notice.
- Liability on the part of wenglor is excluded in the case of:
 - Non-observance of the instructions
 - Use of the product for other than its intended purpose
 - Use of untrained personnel
 - Use of unapproved replacement parts
 - Unapproved modification of products

1.4. Copyrights

- The contents of these instructions are protected by copyright law.
- All rights are reserved by wenglor.
- Commercial duplication or any other commercial use of the content and information made available in these instructions, including graphics and images as well, is prohibited without obtaining written permission from wenglor.

2. For Your Safety

2.1. Use for Intended Purpose

The product is based on the following functional principle:

Contactless Temperature Measurement

The temperature sensor measures infrared radiation emitted by an object in a contactless fashion, on the basis of which it determines the object's temperature. The sensor detects all objects within its working range which emit adequate amounts of infrared radiation within a spectral range of 8 to 14 μm .

The product can be used in the following industry sectors:

- Special machinery manufacturing
- Heavy equipment manufacturing
- Logistics
- Automotive industry
- Food industry
- Packaging industry
- Pharmaceuticals industry
- Clothing industry
- Plastics industry
- Woodworking industry
- Consumer goods industry
- Paper Industry
- Electronics industry
- Glass industry
- Steel industry
- Printing industry
- Aviation industry
- Construction industry
- Chemicals industry
- Agriculture industry
- Alternative energy
- Raw materials production
- Others

2.2. Use for Other than the Intended Purpose

- No safety components in accordance with the machinery directive
- The product is not suitable for use in potentially explosive atmospheres.
- Only accessories obtained from or approved by wenglor may be used with the product.



Danger!

Danger of property damage in the event of use for other than the intended purpose!

Damage to the sensor and other components.
– Use the product for its intended purpose only.

2.3. Personnel Qualifications

- Suitable technical training is a prerequisite.
- Electrotechnical training within the company is required.
- Qualified personnel must have uninterrupted access to the operating instructions.



Caution!

Danger of property damage and personal injury in the event of improper initial start-up and maintenance!

– Train and qualify personnel adequately.

2.4. Modification of Products



Note!

Modification of the product is prohibited.
Nonobservance may result in loss of the CE mark, and may render the guarantee null and void.

2.5. General Safety Precautions



Note!

- These instructions are an integral part of the product and must be kept on hand for the entire duration of its service life.
- Read the operating instructions carefully before using the product.
- Protect the sensor against contamination and mechanical influences.

2.6. Laser/LED Warnings



Laser Class 1 (EN 60825-1)

Standards and safety regulations must be complied with.

2.7. Approvals and Protection Class



3. Technical Data

Order Number	TIF352U0089
Technical Data	
Temperature Data	
Working range	-25...350° C (-13...662° F)
Measuring range	375° C (675° F)
Spectral sensitivity	8...14 μm
Switching hysteresis	1 K
Aperture angle:	10°
Emission factor	0.10...1.00
Settling time (warm-up time)	200 ms
Electrical Data	
Supply power	18...30 V DC
Current consumption (operating voltage = 24 V)	< 60 mA
Switching frequency	≤ 15 Hz (at a response time of 0.065 s)
Response time	0.065...30 s
Temperature range	-20...60° C
Temperature drift (-20° C < T _a ≤ 0° C); T _{Obj} = 150° C	< 0.63 °C/K
Temperature drift (0° C < T _a ≤ 60° C); T _{Obj} = 150° C	< 0.14 °C/K
Number of switching outputs	2
Switching output switching current	200 mA
Analog output	0...10 V
Analog output	4...20 mA
Reproducibility	2.5 K
Linearity error (-25° C < T _{Obj} ≤ 350° C); T _a = 20° C	3.4 K
Linearity error (-20° C < T _{Obj} ≤ 200° C); T _a = 20° C	0.7 K
Service life (T _a = 25° C)	100,000 hours
Laser class (EN 60825-1)	1
Short-circuit proof	Yes
Reverse polarity protected and overload proof	Yes
Interface	RS 232
Baud rate	38,400 baud


Mechanical Data	
Housing material	Stainless steel 1.4305
Protection	IP67
Connector type	8-pin M12×1 plug
Protection class	III
Setting method	Menu-driven via 2-key control panel
Output Function	
Analog output	Yes
Can be switched to NC or NO operation	Yes
Programmable as PNP/NPN	Yes

The following table specifies tightening torques for plugs and mounting options in order to assure compliant, error-free operation:

Connector Type	Tightening Torque (Nm)
M12	0.4


3.1. Field of Vision

The object to be measured must be at least as large as the sensor's field of vision.




SF = width of the field of vision, OA = distance to object

3.2. Housing Dimensions



1 = lens
2 = laser

3.3. Connection Diagram



Legend


+	Supply Voltage +	nc	not connected	ENa	Encoder A
-	Supply Voltage 0 V	U	Test Input	ENb	Encoder B
~	Supply Voltage (AC Voltage)	Ū	Test Input inverted	AMIN	Digital output MIN
A	Switching Output (NO)	W	Trigger Input	AMAX	Digital output MAX
Ā	Switching Output (NC)	O	Analog Output	AOK	Digital output OK
V	Contamination/Error Output (NO)	O-	Ground for the Analog Output	SY in	Synchronization In
Ū	Contamination/Error Output (NC)	BZ	Block Discharge	SY OUT	Synchronization OUT
E	Input (analog or digital)	AWV	Valve Output	OLT	Brightness output
T	Teach Input	a	Valve Control Output +	M	Maintenance
Z	Time Delay (activation)	b	Valve Control Output 0 V	Wire Colors according to DIN IEC 757	
S	Shielding	SY	Synchronization	BK	Black
RxD	Interface Receive Path	E+	Receiver-Line	BN	Brown
TxD	Interface Send Path	S+	Emitter-Line	RD	Red
RDY	Ready	±	Grounding	OG	Orange
GND	Ground	SxR	Switching Distance Reduction	YE	Yellow
CL	Clock	Rx+/-	Ethernet Receive Path	GN	Green
E/A	Output/Input programmable	Tx+/-	Ethernet Send Path	BU	Blue
IO-Link	IO-Link	Ba	Interfaces-Bus A(+)/B(-)	VT	Violet
PoE	Power over Ethernet	La	Emitted Light disengageable	GY	Grey
IN	Safety Input	Mag	Magnet activation	WH	White
OSSD	Safety Output	RES	Input confirmation	PK	Pink
Signal	Signal Output	EDM	Contacting Monitoring	GNYE	Green Yellow

3.4. Complementary Products (see catalog)



wenglor offers Connection Technology for field wiring.

Suitable mounting technology no. **130**

Suitable connection technology no. **89**




3.5. Layout



- ① = Lens
- ② = Laser
- ③ = Control Keys
- ④ = Display
- ⑤ = Plug Connector

3.6. Control Panel



- 60 = Display
- 80 = Mode Key / Switching Status Indicator
- 88 = Plus Key / Error Display / Switching Status Indicator

Designation	Status	Function
Mode Key / Switching Status Indicator	Yellow off	Switching point A1 / $\overline{A1}$ off
	Yellow on	Switching point A1 / $\overline{A1}$ on
	Yellow blinking	Sensor enabled The sensor is in the configuration menu.
Plus Key / Error Display / Switching Status Indicator	Yellow off	Switching point A2 / $\overline{A2}$ off
	Yellow on	Switching point A2 / $\overline{A2}$ on
	Yellow blinking	Error

3.7. Scope of Delivery

- TIF352U0089 Temperature Sensor
- 2 hex nuts, M30×1.5
- Quick start

4. Transport and Storage

4.1. Transport

Upon receipt of goods, check for transport damage. If damage is apparent, accept the package conditionally and notify the manufacturer regarding the damage. Then return the package making reference to transport damage.

4.2. Storage

The following points must be taken into consideration with regard to storage:

- Do not store outdoors.
- Store the product in a dry, dust-free environment.
- Protect the product against mechanical impacts.
- Protect the product against direct sunlight.



Attention!
Danger of property damage in the event of improper storage!
 Possible damage to the product.
 – Observe storage requirements.


5. Installation and Electrical Connection

5.1. Installation

- Protect the product from contamination during installation (see also “2.5. General Safety Precautions” on page 7).
- Corresponding electrical and mechanical regulations, standards and safety rules must be complied with.
- Protect the product against mechanical influences.
- Make sure that the sensor is mounted in a mechanically secure fashion.
- If at all possible, mount the sensor at a right angle to the object to be measured. If this is not possible, the emission factor must be adjusted or determined.
- Minimize ambient influences (air drafts, radiation from other objects) by means of appropriate mounting or shielding.
- The aperture angle must be taken into consideration when mounting the sensor.
- Specified torques must be complied with (see “3. Technical Data” on page 8).

Laser Aligning Tool

- The object can be quickly aligned with the help of the integrated laser.
- The laser beam extends over the entire working range parallel to the axis of the field of vision.
- Distance between the two axes: 9.5 mm
- For correct alignment, the center of the object must always be positioned at the specified distance underneath the sensor.
- The laser does not represent the actual field of vision.



SF = width of the field of vision, OA = distance to object



Attention!
Danger of property damage in the event of improper mounting!
 Possible damage to the product.
 – Observe mounting requirements.

5.2. Electrical Connection

- Connect the sensor to 18 to 30 V DC (see “3.3. Connection Diagram” on page 11).

6. Overview of Functions

6.1. Default Settings

Configuration Menu	Submenu	Function
run		Display mode
PlnF	AnA	Analog output
AnA	U	Analog voltage output
A.Lo	–25	4 mA / 0 V = –25° C
A.hI	350	20 mA / 10 V = 350° C
SP1	–25	Switching point = –25° C
OFn1	PnP	PNP switching logic
SL1	nc	Normally closed output function
SP2	350	Switching point 2 = 350° C
OFn2	PnP	PNP switching logic
SL2	no	Normally open output function
EP	OFF	Expert menu off
Lasr ¹	On	Laser on
d.U ¹	°C	Temperature unit of measure: °C
EF ¹	0.95	Emission factor: 0.95
S.EF. ¹	Current object temperature at emission factor 1	Temperature-calibrated reference object
rESP ¹	1.33	Response time = 1.33 s
Ser.O ¹	OFF	RS 232 port off
rES ¹		Reset

¹ Only visible if the expert menu is set to “On”.

6.2. Function Definitions

Designation	Function	Page
run	Display mode	19
PlnF	Set pin function (analog or switching output)	19
AnA	Adjust analog voltage or current output	19
A.Lo	Temperature which corresponds to 4 mA or 0 V at the analog output	20
A.hI	Temperature which corresponds to 20 mA or 10 V at the analog output	20
SP1	Switching point or switching temperature 1	21
OFn1	Select switching logic, for SP1 (PNP or NPN)	21
SL1	Select output function, for SP1 (NC or NO)	21
SP2	Switching point or switching temperature 2	22
OFn2	Select switching logic, for SP2 (PNP or NPN)	22
SL2	Select output function, for SP2 (NC or NO)	22
EP	Expert menu	23
Lasr	Set laser function (laser on or off)	23
d.U	Select temperature unit of measure (degrees Celsius or Fahrenheit)	24
EF	Adjust emission factor	24
S.EF.	Teach in emission factor	24
rESP	Adjust response time	25
Ser.O	Switch RS 232 port on or off	25
rES	Reset: restore default settings	25

6.3. Menu Structure

Action	Procedure
Enable	Enabling takes place after pressing and holding the M key for roughly 5 seconds. After 5 seconds, the M key LED starts blinking and the sensor is in the configuration menu.
Navigation	After enabling, you can navigate through the configuration menu by briefly tapping the M key repeatedly. The next menu item appears at the display each time the key is tapped. The current setting in the submenu can be displayed by acknowledging with the + key. If the + key is pressed once again, the respective setting is changed.
Change the setting	If a submenu has been accessed, the current setting is displayed after acknowledging with the + key. If the + key is pressed again, the value is changed or the numeric value is increased. Scrolling quickly through the values can be initiated by pressing and holding the key for more than 3 seconds. After scrolling to the last possible setting for the respective submenu (e.g. 350° C), the values start over again from the beginning (e.g. -25° C). A brief pause in scrolling upon reaching the first setting (e.g. -25° C) indicates that the lowest value has been reached.
Save	Pressing the M key not only advances the display to the next menu item: values changed with the + key in the respective submenu are saved at the same time as well. If the M key is pressed when a submenu is open, the display is returned to the configuration menu.

Lock	The configuration menu can be exited by pressing and holding the M key for roughly 5 seconds, after which the current temperature value is displayed along with the selected settings. If no keys are activated for more than 1 minute, the standard display appears. The last change which has not been acknowledged is lost.
------	---

Important: Do not use any sharp objects to press the keys when configuring settings, because they might otherwise be damaged.




Attention!

Danger of property damage in the event that sharp objects are used!

Possible damage to the keys.

– Do not use sharp objects to enter settings.

The sensor's configuration menu is laid out as follows:



¹ Only visible if the pin function is set to "AnA".

² Only visible if the pin function is set to "SP".

7. Settings

7.1. run (display mode)



You can immediately switch to the display mode by pressing the + key.

7.2. PlnF (pin function)



Setting	Description
AnA	Analog Output
	Use of the analog output (pin 6 is used as an analog output). Output type (AnA) and temperature for 4 mA/0 V (A.Lo) and 20 mA/10 V (A.hI) must be selected.
SP	Switching Outputs
	Use of the switching output (pin 6 is used as switching output 2). Switching points (SP1, SP2), output function (OFn1, OFn2) and switching logic (SL1, SL2) must be selected.

7.3. AnA (select analog voltage output or current output)




Setting	Description
U	Voltage Output
	Temperature is read out at the analog output as a voltage value within a range of 0 V to 10 V.
I	Current Output
	Temperature is read out at the analog output as a current value within a range of 4 mA to 20 mA.

7.4. A.Lo (temperature for 4 mA/0 V)

A.Lo

Setting	Description
Value in °C (°F)	Temperature which Corresponds to 4 mA/0 V at the Analog Output
183.0	Value within a range of -25...350° C (-13...662° F).



7.5. A.hi (temperature for 20 mA/10 V)

A.hi

Setting	Description
Value in °C (°F)	Temperature which Corresponds to 20 mA/10 V at the Analog Output
215.0	Value within a range of -25...350° C (-13...662° F).

7.6. SP1 (set switching point or switching temperature 1)

SP1

Set the switching point for switching output A1/ $\overline{A1}$.

Setting	Description
Value in °C (°F)	Switching Temperature 1
-5.0	Value within a range of -25...350° C (-13...662° F). Mode key LED / switching status indicator lights up when set to ON.

7.7. OFn1 (select output function)

OFn1

Select the output function for switching output A1/ $\overline{A1}$.

Setting	Description
PnP	PNP Output
PnP	The load is connected between the minus pole and the output. When switched, the output is connected to the plus pole via an electronic switch.
nPn	NPN Output
nPn	The load is connected between the plus pole and the output. When switched, the output is connected to the minus pole via an electronic switch.

7.8. SL1 (select switching logic)

SL1

Select switching logic for switching output A1/ $\overline{A1}$.

Setting	Description
no	Normally Open (NO)
no	The switching output is set to ON when the measured object temperature is <u>higher</u> than the selected switching point (SP1). The switching output is set to OFF when the measured object temperature is <u>lower</u> than the selected switching point (SP1).
nc	Normally Closed (NC)
nc	The switching output is set to ON when the measured object temperature is <u>lower</u> than the selected switching point (SP1). The switching output is set to OFF when the measured object temperature is <u>higher</u> than the selected switching point (SP1).

7.9. SP2 (set switching point or switching temperature 2)



Set the switching point for switching output A2/ $\overline{A2}$.

Setting	Description
Value in °C (°F)	Switching Temperature 2
183.0	Value within a range of -25...350° C (-13...662° F). Plus key LED / error display / switching status indicator lights up when set to ON.

7.10. OFn2 (select output function)



Select the output function for switching output A2/ $\overline{A2}$.

Setting	Description
PnP	PNP Output
PnP	The load is connected between the minus pole and the output. When switched, the output is connected to the plus pole via an electronic switch.
nPn	NPN Output
nPn	The load is connected between the plus pole and the output. When switched, the output is connected to the minus pole via an electronic switch.

7.11. SL2 (select switching logic)



Select switching logic for switching output A2/ $\overline{A2}$.

Setting	Description
no	Normally Open (NO)
no	The switching output is set to ON when the measured object temperature is <u>higher</u> than the selected switching point (SP2). The switching output is set to OFF when the measured object temperature is <u>lower</u> than the selected switching point (SP2).
nc	Normally Closed (NC)
nc	The switching output is set to ON when the measured object temperature is <u>lower</u> than the selected switching point (SP2). The switching output is set to OFF when the measured object temperature is <u>higher</u> than the selected switching point (SP2).

7.12. EP (expert menu)



Different menu items and submenu items appear depending on whether the expert menu is set to ON or OFF. The expert menu is set to OFF as a default value. The menu is shorter and easier to use as a result. If the displayed menu items are insufficient for the respective application, the expert menu can be switched on in order to be able to take advantage of the sensor's full scope of functions.

Setting	Description
On	Expert Menu On
On	The expert menu is switched on and all menu items can be viewed.
OFF	Expert Menu Off
OFF	The expert menu is switched off and only a few menu items can be viewed.



7.13. Lasr (set laser function)



Setting	Description
On	Laser On
On	The laser is switched on.
OFF	Laser Off
OFF	The laser is switched off.


7.14. d.U (select temperature unit of measure)



Setting	Description
°C	Metric Unit of Measure for Temperature
	The temperature is read out in °C.
°F	Imperial Unit of Measure for Temperature
	The temperature is read out in °F.


7.15. EF (adjust emission factor)



Setting	Description
EF	Adjust Emission Factor
	The emission factor can be set within a range of 0.1 to 1 in steps of 0.01. The emission factor must be accurately adjusted in order to obtain a precise temperature measurement. The emission factor should be set as high as possible, and should not be less than 0.25. See "Emission Factor" on page 28 regarding selected materials and options for determining emission factors. If the emission factor has been adjusted and saved, "S.EF" is deactivated. The last saved value is valid.



7.16. S.EF (determine emission factor with a reference device)



Setting	Description
Value in °C (°F)	Teach In Emission Factor
	Teach in the object temperature using values within a range of -25...350° C (-13... 662° F). If the emission factor of the object to be measured is unknown, it can be determined automatically by entering the object's temperature (ascertain temperature with the help of a contact sensor, for example). If "S.EF" has been adjusted and saved, "EF" is deactivated. The last saved value is valid. No temperatures can be taught in with an emission factor of greater than 1.0 or less than 0.1.

7.17. rESP (set response time)



Setting	Description
Value in s	Response time can be set to one of the following values:
	0.065 s, 0.10 s, 0.34 s, 1.10 s, 1.33 s, 3.00 s, 5.00 s, 10.00 s, 30.00 s The higher the response time setting, the greater the extent to which temperature peaks and fluctuations can be filtered. Adjusting response time changes the switching frequency.
	 NOTE! Switching frequency is reduced as response time is increased.



7.18. SEr.O (activate or deactivate the serial port)




The sensor is equipped with an RS 232 port for communication with a device such as a PC or a controller.
All sensor settings can be selected digitally with a PC, and all values generated by the sensor can be read out at a PC.


Interface configuration:

Baud rate: 38,400 baud, COM: 34800,n,8,1


Setting	Description
On	RS 232 Port On
	The sensor can be connected to a computer via the port.
OFF	RS 232 Port Off
	The sensor is operated without the serial port.

7.19. rES (reset)



Setting	Description
rES	Affected sensor setting are returned to their default values.
	<ul style="list-style-type: none"> Press and hold the + key for roughly 5 seconds. "rESE" appears at the display to confirm that resetting has been successfully completed. The sensor is then returned to normal operation (temperature display) with its default settings.

7.20. Diagnostics

Display	Description	Corrective Measure
	Object temperature outside of the working range.	The temperature of the object must lie within the working range.

In the event of an error, the plus key LED / error display / switching status indicator blinks.

8. RS 232 Port

Process and parameter data can be accessed in the download area for the product at www.wenglor.com.

9. Maintenance Instructions



Note!

- This wenglor sensor is maintenance-free.
- It's advisable to clean the lens and the display, and to check plug connections at regular intervals.
- Do not clean the sensor with solvents or cleansers which could damage the product.
- Contamination on the lens results in incorrect measured values.
- The lens must therefore be inspected at regular intervals and cleaned when necessary.
- Dust should be removed first with an air jet or a soft brush.
- Clean, soft, lint-free cloths are also suitable.
- As little pressure as possible should be applied to the lens during cleaning, in order to avoid scratching.

10. Proper Disposal

wenglor sensoric GmbH does not accept the return of unusable or irreparable products. Respectively valid national waste disposal regulations apply to product disposal.

11. Exclusion of Liability

wenglor sensoric GmbH, hereinafter referred to as wenglor, makes explicit reference to the fact that the information contained in these operating instructions may be subject to continuous further development and technical changes. These operating instructions do not imply any guarantee from wenglor with regard to the described procedures or specific product characteristics.

wenglor assumes no liability for printing errors or other inaccuracies contained in these operating instructions, unless wenglor was verifiably aware of such errors at the point in time at which the operating instructions were prepared. Furthermore, wenglor herewith explicitly informs the user that these operating instructions are only a general description of technical procedures whose implementation may not be suitable in all cases as described in this document. Information included in these operating instructions is subject to change without notice. No part of this document may be duplicated or translated into any other languages, regardless of the utilized means, without prior written consent from wenglor sensoric GmbH.

Any and all liability, regardless of legal grounds, is excluded insofar as this is legally permissible. In particular with regard to any material and/or legal defects demonstrated by the software or the hardware, as well as associated documentation and information – especially with regard to correctness, accuracy, absence of third party protective rights and copyrights, timeliness, completeness and/or usability – no liability is assumed except in the event of malice aforethought or malicious intent.

12. Appendix

12.1. Operating Instructions Change Index

Version	Date	Description/Change
1.0.0	21 May 2015	Layout revised

12.2. Emission Factor

The following table includes a selection of emission factors provided as examples within a spectral range of 8 to 14 μm at a temperature of 70° C. To a great extent, the actual emission factor depends on the object's surface finish (especially in the case of metals).

Material	Specification	Emission Factor
Aluminum	Sheet	0.03...0.06
Aluminum	Anodized, light gray, dull	0.95...0.97
Aluminum	Cast, sandblasted	0.46
Bronze	Phosphor bronze	0.06
Stainless steel	Polished	0.07
Galvanized iron	Sheet, oxidized	0.85
Iron and steel	Cold rolled	0.09
Fiberboard	Chloritoid	0.88
Fiberboard	Particle board	0.89
Veneer	Oak parquet floor as well	0.90...0.93
Granite	Rough	0.77...0.87
Wood	Planed oak	0.88
Plastic	Fiberglass laminate (PCB)	0.91
Plastic	PVC, dull, textured	0.93
Paint	3 colors sprayed onto aluminum	0.92...0.94
Paint	8 different colors and qualities	0.92...0.94
Brass	Oxidized	0.03...0.07
Paper	4 different colors	0.92...0.94
Paper	White, various degrees of gloss	0.88...0.90
Stainless steel	Sheet, untreated	0.28

Determining the Emission Factor

If the material of the object to be measured is known, the values in the table can be used as approximations. Most organic materials such as plastics, textiles and wood have an emission factor of approximately 0.95. In the case of objects made of unknown materials or where highly precise measurements are required, one of the following methods can be used in order to accurately determine the emission factor.

Comparative Measurement


- 1 Measure and make a note of the temperature of the object with the help of a thermocouple or another temperature measuring device which makes contact with the object.
- 2 Adjust the wenglor temperature sensor so that it's aligned to the object. The object must entirely fill out the sensor's field of vision.
- 3 Set the emission factor as described in "7.15. EF (adjust emission factor)" on page 24.

Heat Up to a Known Value

- 1 Heat up the object (or a specimen of the object's material) to a known temperature. The sensor and the air surrounding the specimen must have the same temperature.
- 2 Adjust the wenglor temperature sensor so that it's aligned to the object. The object must entirely fill out the sensor's field of vision.
- 3 Set the emission factor so that the temperature measured in step 1 is displayed.

Mask the Object using a Material with a Known Value

- 1 This method is suitable for objects with temperatures of less than 260° C.
- 2 Cover the object or a specimen of the object's material using masking tape with a known emission factor. Wait long enough for the temperature of the masking tape to adjust to the temperature of the object.
- 3 Set the emission factor at the sensor to the known value of the masking tape. Measure the temperature of the masking tape (surface "A" in the figure below) with the temperature sensor. Make sure that the measured area entirely fills out the sensor's field of vision.



- 4 Adjust the wenglor temperature sensor so that it's aligned to an uncovered area on the object (surface "B" in the figure). Make sure that the measured area entirely fills out the sensor's field of vision. This surface should be as close as possible to the area covered with masking tape.
- 5 Set the emission factor so that the temperature measured in step 3 is displayed.

Paint the Object

- 1 Paint part of the object (or a specimen of the object's material) using a black paint with a known emission factor, and allow the paint to dry.
- 2 Set the emission factor at the sensor to the known value of the paint. Measure the temperature of the painted part of the object (surface "A" in the figure above) with the sensor. Make sure that the measured area entirely fills out the sensor's field of vision.
- 3 Adjust the wenglor temperature sensor so that it's aligned to an unpainted area on the object.
- 4 Set the emission factor so that the temperature measured in step 2 is displayed.

12.3. EC Declaration of Conformity

The EC Declaration of Conformity can be found in the download area for the product on our website at www.wenglor.com.