

Software wenglor

Discovery Tool DNNF022



Release Notes

Change Index Software wenglor Discovery Tool

Version	Release Date	Description	Compatibility
1.2.3	23.01.2025	Minor improvements and bugfixes (e.g. discovery of devices outside the network)	• Firmware B60: 1.4.0 • Firmware MLxS: 1.3.2 • Firmware MVC: 1.1.0
1.2.2	16.12.2024	Bugfix and performance improvements: • Network warning is shown when Machine Vision Device is in a different network and device web-site is not accessible. • Network change for LAN of MVC to reserved IPs is prevented.	• Firmware B60: 1.3.3 • Firmware MLxS: 1.3.1 • Firmware MVC: 1.0.3
1.2.1	05.11.2024	Minor bugfix: The button to access the device website (Open Device) is now enabled if a gateway is used between the Machine Vision Device and the PC with the software wenglor Discovery Tool.	• Firmware B60: 1.3.2 • Firmware MLxS: 1.3.1 • Firmware MVC: 1.0.2
1.2.0	08.08.2024	Support of Machine Vision Controller MVC	• Firmware B60: 1.3.0 • Firmware MLxS: 1.3.0 • Firmware MVC: 1.0.0
1.1.1	02.02.2024	Bugfix: Editing network configuration for 3D Sensors ShapeDrive (MLxS) works again.	• Firmware B60: 1.1.1 • Firmware MLxS: 1.2.0
1.1.0	11.12.2023	Support of several user languages (DE, EN, FR, IT, ES, PT, NL, HU, TR, ZH, RU)	• Firmware B60: 1.1.0 • Firmware MLxS: 1.0.0
1.0.1	19.09.2023	Bugfix: Correct display of several devices at changing network configurations of PC.	• Firmware B60: 1.0.1 • Firmware MLxS: 1.0.0
1.0.0	04.08.2023	Initial version for the market introduction	• Firmware B60: 1.0.0 • Firmware MLxS: 1.0.0